

## Subject: 350 SX-F Main Power Relay

**Affected Models: 2011 350 SX-F**

### Initial Information:

- » Through continuous product development, improvement and testing under certain circumstances, such as extensive lateral forces during jumping and on “whoop sections”, the main power relay could become dismounted from the battery box.
- » To improve the mounting stability under above mentioned extreme riding conditions, KTM recommends to install a cable tie part number **440.11.076.305**, so that the cable tie loops around the subframe and the rubber grommet. Mount as shown in the following pictures. **This is NOT A WARRANTY ITEM!**



#### COPYRIGHT NOTICE

The user acknowledges that all components of this technical information are KTM's and/or third parties' copyright protected property. Alteration, assignment, distribution and reproduction are forbidden.

#### LIMITATION OF LIABILITY

The information included in or available through this technical information may include inaccuracies or errors. In no event shall KTM and/or its suppliers be liable for any damages whatsoever, arising out of or in connection with the use of this technical information. Please always refer to the KTM owners and repair manuals for proper instructions or contact the KTM Dealer Technical Service Department.

**KTM NORTH AMERICA, INC.** EAST » 1119 Milan Avenue » Amherst » Ohio 44001 » Phone 440-985-3553 » Fax 440-985-3060  
Technical Department WEST » 38429 Innovation Court » Murrieta » CA 92563 » Phone 951-600-8007  
CANADA » 1375-1 Marie-Victorin » Saint-Bruno » QC J3V 6B7 » Phone 450-441-4451 » Fax 450-441-3885