

Subject: 350 SX-F First Service at 1 Operating Hour

Affected Models: 2011 350 SX-F

Initial Information:

- » With the inception of the 350 SX-F, a new service schedule must be followed. Please bring this to the attention of your customers and also your dealership staff.
- » As described in the Owners Manual & Repair Manual, the first service should be performed at 1 hour of vehicle operation. During this service it is mandatory for the Engine Oil and Filter to be changed. KTM has packed 2 liters of 10w60 engine oil in the motorcycle crate to be given to the customer during delivery of the 350 SX-F.

Service schedule				
	S1N	S10A	S20A	S30A
Read out the fault memory using the KTM diagnostics tool.		*	*	*
Check and charge the battery.		*	*	*
Change the engine oil and oil filter, clean the oil screen.	*	*	*	*
Check the front brake linings.		*	*	*
Check the rear brake linings.		*	*	*
Check the brake discs.		*	*	*
Check the brake lines for damage and leakage.		*	*	*
Check the rear brake fluid level.		*	*	*
Change the foot brake cylinder seals.			*	
Check the free travel of the foot brake lever.		*	*	*
Check the frame and swingarm.		*	*	*
Check the swingarm bearing.			*	
Check the shock absorber linkage.		*	*	*
Conduct a minor fork service.		*	*	*
Conduct a major fork service.				*
Check the tire condition.	*	*	*	*
Check the tire air pressure.	*	*	*	*
Check the wheel bearing for play.		*	*	*

S1N: Once after 1 service hour - corresponds to about 7 liters of fuel (1.8 US gal)
S10A: Every 10 service hours - corresponds to about 70 liters of fuel (18.5 US gal) / after every race
S20A: Every 20 service hours - corresponds to about 140 liters of fuel (37 US gal)
S30A: Every 30 service hours - corresponds to about 210 liters of fuel (55.5 US gal)

COPYRIGHT NOTICE

The user acknowledges that all components of this technical information are KTM's and/or third parties' copyright protected property. Alteration, assignment, distribution and reproduction are forbidden.

LIMITATION OF LIABILITY

The information included in or available through this technical information may include inaccuracies or errors. In no event shall KTM and/or its suppliers be liable for any damages whatsoever, arising out of or in connection with the use of this technical information. Please always refer to the KTM owners and repair manuals for proper instructions or contact the KTM Dealer Technical Service Department.

KTM NORTH AMERICA, INC. EAST » 1119 Milan Avenue » Amherst » Ohio 44001 » Phone 440-985-3553 » Fax 440-985-3060
 Technical Department WEST » 38429 Innovation Court » Murrieta » CA 92563 » Phone 951-600-8007
 CANADA » 1375-1 Marie-Victorin » Saint-Bruno » QC J3V 6B7 » Phone 450-441-4451 » Fax 450-441-3885